

LIMPIEZA VIARIA:
SEMANA 17/09/2018 AL 21/09/2018.




Maquina sopladora ha seguidos: después de Plaza del ayuntamiento, plaza la estación, y casa la cultura a seguido de avenida hacía bajo.



Maquina sopladora ha estado en Urbanización el Clot.

Urbanización el clot Recogida de enseres y basura.





La Reva repasado de alcantarillado, papeleras, contenedores y avd central, rama caída en Reva y corte de césped en el parque.

Carril Bici Carretera Villamarchante.



La limpiadora despues del parking del consum pasando por la avenida hacia mas de escoto



Els pous de martí donde se asfalto la bajada de la parada del bus.



Zona Santa Rosa recogida de enseres y basura, las rejillas algunas estaban tapadas por hojas.



The collage consists of 20 individual photographs arranged in a grid-like fashion, illustrating various forms of illegal waste disposal and littering. The images show:

- Overflowing and damaged recycling bins (green and blue) with debris scattered around.
- Large piles of construction materials, including bricks and tiles, dumped on the ground.
- Discarded furniture, such as a wooden table and chairs, left on a paved area.
- General trash, including plastic bags, bottles, and food waste, scattered on sidewalks and in open areas.
- Illegal dumping of large items, such as a white sofa or mattress, on the street.
- Overflowing grey waste bins with trash spilling out onto the pavement.
- Discarded construction materials, including pipes and bricks, lying on the ground.
- Large piles of debris and trash in open areas, possibly near a construction site or a park.
- Discarded furniture, including a wooden table and chairs, left on a paved area.
- Overflowing and damaged recycling bins (green and blue) with debris scattered around.
- Large piles of construction materials, including bricks and tiles, dumped on the ground.
- Discarded furniture, such as a wooden table and chairs, left on a paved area.
- General trash, including plastic bags, bottles, and food waste, scattered on sidewalks and in open areas.
- Illegal dumping of large items, such as a white sofa or mattress, on the street.
- Overflowing grey waste bins with trash spilling out onto the pavement.
- Discarded construction materials, including pipes and bricks, lying on the ground.
- Large piles of debris and trash in open areas, possibly near a construction site or a park.



Zona Masia de Traver recogida de enseres, basura y hierbas.

